

MC4000 Firmware Release Notes

v0017

-Fixed Sampler bank selection LED lighting prematurely changing after a bank is selected

v0016

-Fixed incorrect message sent when switching to Sampler bank 2 and triggering Sample Pad 1,2,3,4

v0015

-Initial shipping firmware