

IMPORTANT: X1800 Driver v1.0.5 must be installed prior to updating firmware on Windows. There is a chance that the firmware update could fail on some Windows 10 machines if driver v1.0.5 or later is not installed prior to starting the firmware update.